

CAP Aviation 9, rue de l'Aviation 21121 DAROIS - France Tel +33 380 35 65 10 Fax +33 380 35 65 15 www.capaviation.com	<h1>S E R V I C E B U L L E T I N</h1>	
NUMBER	TITLE	ATA SYSTEM
010402	MICHELIN Tires	324

## 1. PLANNING INFORMATION

### 1.1 Approval

**NOTA:** This document is a courtesy translation of its original French version. Whereas the original French version of the information and instructions is approved, this *translation* is *not* approved.  
As a consequence, the approval mentions below are to be understood as applicable to the *original French version* of this SB.

#### Minor change

This Service Bulletin corresponds to the MINOR change Nr 010402 which has been approved under the privileges of the Design Organisation Approval DGAC Nr° F.JA.06.

The technical information contained in this document is approved under the privileges of the Design Organisation Approval Nr° F.JA.06.

Revision	Date	Description	Airworthiness Office Manager	Head of Design Organisation
			Recommendation for approval	Approval
0	16th april 2001	Original issue		

### 1.2 Effectivity

<b>Aircraft : type</b>	CAP232	CAP10B
<b>Serial Nr</b>	001-999	001-999

<b>Spare parts with Serial Nr</b>	Non applicable	Non applicable
<b>Serial Nr</b>	Non applicable	Non applicable

### 1.3 Implementation

	SERVICE BULLETIN	DELAI D'APPLICATION
X	Optional	For information
	Recommended	
	Mandatory	

### 1.4 Reason

Give the choice to users between two tires : MICHELIN Tires and GOODYEAR Tires

### 1.5 Description

On the CAP10B :

For information, the user can install MICHELIN Tires 380x150-5-6PR (P/N : 070-544-0). He still has the possibility to use GOODYEAR Tires which are in service today.

On the CAP232 :

For information, the user can install MICHELIN Tires 5.00x5-6PRTT (P/N : 070-312-0). He still has the possibility to use GOODYEAR Tires which are in service today.

### 1.6 Manpower

N/A

### 1.7 Material

The new and modified parts make up the material, and are mentioned in the chapter 0 of this Service Bulletin. Spare parts are to be supplied at ASCO Aviation Service Centre (Tel : +33 380 35 61 98, Fax : +33 380 35 60 58).

### 1.8 Tooling

Standard tooling

### 1.9 Weight and balance

#### 1.9.1 Aircraft

N/A.

#### 1.9.2 Engine

N/A.

#### 1.9.3 Accessories or components for aircraft use

N/A.

### 1.10 References

N/A.

## 1.11 Affected publications

### For CAP232 :

- A copy of this Service Bulletin must be inserted in the CAP232 Illustrated Parts Catalogue, until the next annual update if this document.
- Service Letter Nr 990813: User Documents List.

### For CAP10B :

- A copy of this Service Bulletin must be inserted in the CAP10B Illustrated Parts Catalogue.
- Service Letter Nr 990813: User Documents List.

## 1.12 Feedback

You can use:

- postal mail : address on the first page of this Service Bulletin,
- fax : (+33) (0) 380 35 6515,
- e-mail : [caroline.morel@capaviation.com](mailto:caroline.morel@capaviation.com),
- the web page of Cap Aviation : <http://www.capaviation.com>.

## 1.13 Appendices

N/A

## 2. ACCOMPLISHMENT INSTRUCTIONS

The two tires shall be replaced at the same time. The two tires, installed on the aeroplane, shall have the same trade-mark ; no mix is possible between GOODYEAR and MICHELIN.  
The tube and the tire shall have the same trade-mark.

## 3. MATERIAL INFORMATION

New P/N.	Quantity	Key word	Old P/N.	Instructions
P/N 385M61-1	2	GOODYEAR Tire	P/N 385M61-1	To replace if needed
P/N 505C66-1	2	GOODYEAR Tire	P/N 505C66-1	To replace if needed
380x150-5/5.00-5 TR67	2	GOODYEAR Tube	380x150-5/5.00-5 TR67	To replace if needed
P/N 070-544-0	2	MICHELIN Tire	—	To replace if needed
P/N 070-312-0	2	MICHELIN Tire	—	To replace if needed
P/N 092-308-0	2	MICHELIN Tube	—	To replace if needed

*For current prices, please contact ASCO Aviation Service Center.*