



APEX Aircraft Bureau de navigabilité 9, rue de l'Aviation 21121 DAROIS - France Tel +33 380 35 65 10 Fax +33 380 35 65 15 www.apex-aircraft.com		<h1>S E R V I C E B U L L E T I N</h1>
NUMBER	TITLE	ATA SYSTEM
15	CAP10B wing – main spar inspection	57

## 1. PLANNING INFORMATION

### 1.1 Approval

**NOTA:** This document is a courtesy translation of its original French version. Whereas the original French version of the information and instructions is approved, this *translation* is *not* approved.  
 As a consequence, the approval mentions below are to be understood as applicable to the *original French version* of this SB.

The technical information contained in this document is approved under the privileges of the Design Organisation Approval Nr° F.JA.06.

Revision	Date	Description	Airworthiness Office Manager	Head of Design Organisation
			Recommendation for approval	Approval
2	April 2 <sup>nd</sup> , 02	Cancellation of Service Bulletin 15		

### 1.2 Effectivity

<b>Aircraft : type</b>	CAP10B	
<b>Serial Nr</b>	001 to 282	

### 1.3 Implementation

	SERVICE BULLETIN	IMPLEMENTATION DELAY
<b>X</b>	Mandatory	During the next maintenance operation

### 1.4 Reason

Cancellation of SB 15, revision 1. The inspection previously described in this Service Bulletin have been integrated into the new inspection schedule, edition 1, dated March 1<sup>st</sup> 2002.