



SERVICE BULLETIN n°980901

9, route de l'Aviation
21121 DAROIS
Tel 03 80 35 65 10
Fax 03 80 35 65 15

ATA SYSTEM : 27
EFFECTIVITY : CAP231ex - 232
TITLE : Trim tab control axis

Issue	Revision	Date	Reason for change	Visa
0	0	30/09/98	Original Issue	

1. PLANNING INFORMATION

1.1. EFFECTIVITY

Aircraft	CAP231ex	CAP232	
Serial n°	02-06	All	

1.2. REASON

	SERVICE BULLETIN	DELAY FOR APPLICATION
	Optional	
	Recommended	
X	Mandatory	As indicating in the "Programme d'Entretien CAP 231 ex & 232", Revision 1, Issue 2

To guaranty the reliability of the trim tab control axis after the incident n°001/98/AKROTECH reported on the 05/07/98 by the GSAC Dijon.

1.3. DESCRIPTION

To limit the life of the part at **400 hours**.

1.4. APPROVAL

This Service Bulletin has been reviewed by the DGAC by the letter ref. 986276/SFACT/N.AG and the modification herein complies with FAR23 amendment 12 and is APPROVED for the installation in the CAP231ex and CAP232.

1.5. MANPOWER

None.

1.6. MATERIAL

The new parts are available at MABAS'.
(Tel : +0033 2 32 46 00 23, Fax : +0033 2 32 44 47 69)

1.7. TOOLING

None.

1.8. WEIGHT & BALANCE

1.8.1. Aircraft

None.

9, route de l'Aviation
 21121 DAROIS
 Tel 03 80 35 65 10
 Fax 03 80 35 65 15

ATA SYSTEM : 27
 EFFECTIVITY : CAP231ex - 232
 TITLE : Trim tab control axis

1.8.2. Engine

None.

1.8.3. Accessory or Component for aircraft use

None.

1.9. ELECTRICAL LOAD DATA

None.

1.10. REFERENCES

Inspection Programme CAP231ex & 232, edition 2, revision 1 of 30/09/98 :

- Page I
- Page II
- Page 3.2
- Page 6.4

2. ACCOMPLISHMENT INSTRUCTIONS

None.

3. MATERIAL INFORMATION

New P/N	Quantity	Unit list price	Key word	Old P/N	Instructions
2734-9220401	1	260 FHT	Trim tab control axis	2734-9220401	Life limit at 400 hours

