

CAP Aviation 9, rue de l'Aviation 21121 DAROIS - France Tel +33 380 35 65 10 Fax +33 380 35 65 15 www.capaviation.com	<h1>S E R V I C E B U L L E T I N</h1>	
NUMBER	TITLE	ATA SYSTEM
990701	Brake linings references	32

1. PLANNING INFORMATION

1.1 Approval

NOTA: This document is a courtesy translation of its original French version. Whereas the original French version of the information and instructions is approved, this *translation* is *not* approved.
 As a consequence, the approval mentions below are to be understood as applicable to the *original French version* of this SB.

This Service Bulletin corresponds to the MAJOR change Nr 990701 which has been approved by the DGAC.

The technical information contained in this document is approved under the privileges of the Design Organisation Agreement Nr° F.JA.06.

Revision	Date	Description	Airworthiness Office Manager	Head of Design Organisation
			Recommendation for approval	Approval
0	26/07/2000	Original issue		

1.2 Effectivity

Aircraft : type	CAP10B
Serial Nr	Up to # 268 included

Spare parts with Serial Nr	N/A
Serial Nr	N/A

1.2.1 For information :

The change corresponding to this Service Bulletin has been implemented during serial manufacturing:

Aircraft : Type	N/A
Serial Nr	N/A

Spare parts with Serial Nr	N/A
Serial Nr	N/A

1.3 Implementation

	SERVICE BULLETIN	DELAI D'APPLICATION
X	Optional	No delay – For information.
	Recommended	
	Mandatory	

1.4 Reason

Inform users about the new brake linings references.

1.5 Description

From now on, the lining are bonded and riveted on the brake plates.
The brake linings are no more available separately.
The brake plate reference corresponds to the assembly "plate + lining".

1.6 Manpower

None.

1.7 Material

The new and modified parts make up the material, and are mentioned in the chapter 3 of this Service Bulletin.

Spare parts are to be supplied at ASCO Aviation Service Centre (Tel : +33 380 35 61 98, Fax : +33 380 35 60 58).

1.8 Tooling

None.

1.9 Weight and balance

1.9.1 Aircraft

None.

1.9.2 Engine

None.

1.9.3 Accessories or components for aircraft use

None.

1.10 References

None.

1.11 Affected publications

- A copy of this Service Bulletin must be inserted in the CAP10B Illustrated Parts Catalogue.
- Service Letter Nr 990813: User Documents List.

1.12 Feedback

- postal mail : address on the first page of this Service Bulletin,
- fax : (+33) (0) 380 35 6515,
- e-mail : caroline.morel@capaviation.com,
- the web page of Cap Aviation : <http://www.capaviation.com>.

1.13 Appendices

None.

2. ACCOMPLISHMENT INSTRUCTIONS

None.

3. MATERIAL INFORMATION

New P/N.	Quantity	Unit list price	Key word	Old P/N.	Instructions
3243-9405006A	2	243,95 FHT	Brake plate	3243-9405006	To be replaced
3243-9405006A	2	243,95 FHT	Brake plate	CAP10-40-64-04	To be replaced
			Plate	3244-9405007	Not available separately
			Lining	3244-9405008	Not available separately

This table has no contract value. Prices are given for information only and can be modified without previous notice. For current prices, please contact ASCO Aviation Service Center.