

CAP Aviation 9, rue de l'Aviation 21121 DAROIS – France Tel +33 380 35 65 10 Fax +33 380 35 65 15 Www.capaviation.com		<h1>S E R V I C E B U L L E T I N</h1>
NUMBER	TITLE	ATA SYSTEM
000703	Safety belt references	25

1. PLANNING INFORMATION

1.1 Approval

NOTA: This document is a courtesy translation of its original French version. Whereas the original French version of the information and instructions is approved, this *translation* is *not* approved.
 As a consequence, the approval mentions below are to be understood as applicable to the *original French version* of this SB.

This Service Bulletin corresponds to the MINOR change Nr 000703 which has been approved under the privileges of the Design Organisation Agreement DGAC Nr° F.JA.06.

The technical information contained in this document is approved under the privileges of the Design Organisation Agreement Nr° F.JA.06.

Revision	Date	Description	Airworthiness Office Manager	Head of Design Organisation
			Recommendation for approval	Approval
0	24/07/2000	Original issue		

1.2 Effectivity

Aircraft : type	CAP232	CAP10B	CAP20L	CAP21	CAP231
Serial Nr	001-999	001-999	001-999	001-999	001-999

Spare parts with Serial Nr	N/A
Serial Nr	N/A

1.2.1 For information :

The change corresponding to this Service Bulletin has been implemented during serial manufacturing:

Aircraft : Type	CAP232
Serial Nr	023-999

Spare parts with Serial Nr	N/A
Serial Nr	N/A

1.3 Implementation

	SERVICE BULLETIN	DELAY OF IMPLEMENTATION
X	Optional	No delay - For information
	Recommended	
	Mandatory	

1.4 Reason

Inform the users about the new references of the safety belts.

1.5 Description

None.

1.6 Manpower

None.

1.7 Material

The new and modified parts make up the material, and are mentioned in the chapter 3 of this Service Bulletin.

Spare parts are to be supplied at ASCO Aviation Service Centre (Tel : +33 380 35 61 98, Fax : +33 380 35 60 58).

1.8 Tooling

None.

1.9 Weight and balance

1.9.1 Aircraft

None.

1.9.2 Engine

None.

1.9.3 Accessories or components for aircraft use

None.

1.10 References

None.

1.11 Affected publications

- A copy of this Service Bulletin must be inserted in the CAP10B, CAP20L, CAP21 and CAP231 Illustrated Parts Catalogues.
- Service Letter Nr 990813: User Documents List.

1.12 Feedback

- postal mail : address on the first page of this Service Bulletin,
- fax : (+33) (0) 380 35 6515,
- e-mail : caroline.morel@capaviation.com,
- the web page of Cap Aviation : <http://www.capaviation.com>.

1.13 Appendices

None.

2. ACCOMPLISHMENT INSTRUCTIONS

None.

3. MATERIAL INFORMATION

New P/N.	Quantity	Unit list price	Key word	Old P/N.	Instructions
3491203-12-007	1	476 FHT	Safety belt	343-11202103538	Interchangeable
3491112-12-222	1	476 FHT	Safety belt	343-11202104147	Interchangeable

This table has no contract value. Prices are given for information only and can be modified without previous notice. For current prices, please contact ASCO Aviation Service Center.